

**Cleanolyte CE 3**

Material number 81.5403.1

Field of activity:

**Hazard to man and environment****Xi**

irritant

R 36/37/38

Irritating to eyes, respiratory system and skin.

**Preventive measures and rules of conduct**

S 23

S 24/25

S 26



S 36/37/39

S 45

Do not breathe vapour or spray.

Avoid contact with skin and eyes.

In case of contact with eyes, rinse immediately with plenty of water and seek medical advice.

Wear suitable protective clothing, gloves and eye/face protection.

In case of accident or if you feel unwell, seek medical advice immediately (show this label if possible).

Provide good ventilation and/or an exhaust system in the work area.

Persons working with this product should not wear contact lenses.

Avoid contact with eyes. Avoid prolonged or repeated contact with skin. Remove contaminated clothing. Do not breathe vapour or spray.

Wash hands before breaks and at the end of work.

Have eye wash bottle or eye rinse ready at work place.

Respiratory protection:

Respiratory protection must be worn whenever the WEL levels have been exceeded.

Combination filter B-P2 according to EN 141.

Hand protection:

Protective gloves according to EN 374.

Glove material: Nitrile rubber-Layer thickness:  $\geq 0,35$  mm

Possible alternatives: Natural rubber (caoutchouc), butyl rubber, fluororubber.

Breakthrough time:  $> 480$  min.

Observe glove manufacturer's instructions concerning penetrability and breakthrough time.

Eye protection:

Tightly sealed safety glasses according to EN 166.

Skin protection:

Wear suitable protective clothing.

**Reaction in case of danger**

Provide good ventilation. Do not breathe vapour or spray.

Avoid contact with the substance. Wear suitable protective clothing.

Accidental release measures:

Absorb with liquid-binding material (e.g. sand, diatomaceous earth, acid- or universal binding agents) and place in closed containers for disposal. Use soda or another alkaline detergent for removal of residues.

# OPERATING DIRECTIVE

according to § 20 GefStoffV (Germany)

Date of print: 27.01.2010


Page: 2 of 2

## Cleanolyte CE 3

Material number 81.5403.1

Field of activity:

### First aid

General information:	Remove contaminated clothing.	
Following inhalation:	Provide fresh air. In case of respiratory difficulties seek medical attention.	
After skin contact:	Immediately clean with water and soap and, if available, apply a generous amount of polyethylene glycol 400. In case of skin reactions, consult a physician.	
After eye contact:	Immediately flush eyes with plenty of flowing water for 10 to 15 minutes holding eyelids apart. Subsequently consult an ophthalmologist.	
After swallowing:	Rinse mouth and drink large quantities of water. Do not induce vomiting. Risk of perforation! Immediately get medical attention.	

### Appropriate disposal

Waste key number (EU)	110106* acids not otherwise specified * = Evidence for disposal must be provided.
Product:	Waste disposal according to official state regulations.
Waste key number (EU)	150102 Plastic packaging
Contaminated packaging:	Waste disposal according to official state regulations. Handle contaminated packaging in the same way as the substance itself.