

Neutralyte N 10

Material number 22.110

Field of activity:

Hazard to man and environment



Xi

irritant

R 41

Risk of serious damage to eyes.

Preventive measures and rules of conduct



S 25

Avoid contact with eyes.

S 26

In case of contact with eyes, rinse immediately with plenty of water and seek medical advice.

S 39

Wear eye/face protection.



Vapours/aerosols should be exhausted directly at the point of origin.

Change contaminated clothing.

Wash hands before breaks and after work.

Have eye wash bottle or eye rinse ready at work place.

Respiratory protection:

Respiratory protection must be worn whenever the WEL levels have been exceeded.

Use filter type A (= against vapours of organic substances) according to EN 141.

Hand protection:

Protective gloves according to EN 374.

Glove material: Nitrile rubber or butyl caoutchouc (butyl rubber).

Observe glove manufacturer's instructions concerning penetrability and breakthrough time.

eye protection:

Tightly sealed safety glasses according to EN 166

Body protection:

Light protective clothing

Reaction in case of danger

Avoid contact with the substance. Wear suitable protective clothing.

Accidental release measures:

Soak up with absorbent materials such as sand, siliceus earth, acid- or universal binder. Store in special closed containers and dispose of according to ordinance. Wash spill area with plenty of water.

First aid

After inhalation:

Move victim to fresh air. In case of respiratory difficulties seek medical attention.

In case of skin contact:

Remove residues with soap and water.

Change contaminated clothing. In case of skin irritation, consult a physician.

After eye contact:

Immediately flush eyes with plenty of flowing water for 10 to 15 minutes holding eyelids apart. Subsequently seek the immediate attention of an ophthalmologist.

After swallowing:

Rinse mouth thoroughly with water. Give water to drink in small sips.

Never give anything by mouth to an unconscious person.

Do NOT induce vomiting. Risk of foam aspiration when vomiting.

Immediately get medical attention.



OPERATING DIRECTIVE

according to § 20 GefStoffV (Germany)

Date of print: 19.10.2010
Page: 2 of 2

Neutralyte N 10

Material number 22.110

Field of activity:

Appropriate disposal

Waste key number (EU) 110107*

pickling bases

* = Evidence for disposal must be provided.

Product:

Special waste. Dispose of waste according to applicable legislation.

Waste key number (EU) 150102

Plastic packaging

Contaminated packaging:

Dispose of waste according to applicable legislation.

Non-contaminated packages may be recycled.